

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 9/20/2022 **Time:** 9:23 AM
Name of School Corporation: WHITKO COMMUNITY SCHOOL CORP. **Corp ID:** 434455
Address of School Corporation: PO Box 114
City: Pierceton **Zip:** 46562 **County Number:** 92
VIN: 1GB6G3AG0A1141332 **License Number:** 83154 **Bus Number:** W2
Make of Body: Collins Bus Corporation **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: A1 **Mileage:** 165960
Inspection Status: O **Inspected By:** Joseph Hartman **PE:** 7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**