REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	9/19/2022	**Time:**	11:15 AM
Name of School Corporation:	GREENCASTLE COMMUNITY CORP.			**Corp ID:**	676755
Address of School Corporation:	PO Box 480				
City:	Greencastle	**Zip:**	46135	**County Number:**	67
VIN:	1BABNBPA7FF308416	**License Number:**	7292	**Bus Number:**	2
Make of Body:	Blue Bird Corporation **Year:** 2014	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2015
Bus Type:	D	**Mileage:**	90702		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.