

## REPORT OF SCHOOL BUS INSPECTION

|  |                                  |   |
|--|----------------------------------|---|
| <b>Type of Inspection:</b> Annual                                  | <b>Date:</b> 9/28/2022           | <b>Time:</b> 9:38 AM                          |
| <b>Name of School Corporation:</b> INTERNATIONAL LEADERSHIP SCHOOL | <b>Corp ID:</b> ILS02            |   |
| <b>Address of School Corporation:</b> 6413 N Clinton               |                                  |   |
| <b>City:</b> Fort Wayne  | <b>Zip:</b> 46825                | <b>County Number:</b> 2                       |
| <b>VIN:</b> 1BABNCPA5DF292140                                      | <b>License Number:</b> B217T     | <b>Bus Number:</b> 183                        |
| <b>Make of Body:</b> Blue Bird Corporation                         | <b>Year:</b> 2012                | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Bus Type:</b> D   | <b>Mileage:</b> 101883           | <b>Year:</b> 2012                             |
| <b>Inspection Status:</b> R  | <b>Inspected By:</b> Eric Egbert | <b>PE:</b> 7006                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 54-1-1                 | Stanchions, guardrails, guard panels or barriers are insecurely attached   |
| 44-1-1                 | Any marker light or lens is missing, cracked, faded, wrong color, or inoperative   |
| 28-1-2                 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |
| 46-1-3                 | Any required padding is missing  |
| 103-1-1                | See Notes: Any defect inspector deems a violation not listed   |
| 26-1-2                 | Not fully charged  |
| 41-1-5                 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)   |
| 56-1-2                 | There are attachments to the wheel   |
| 57-1-5                 | Step-well light is missing or inoperative  |
| 50-1-2                 | The seat belt cutter is not secured using a positive fastening method.   |

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.