

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	9/28/2022	<b>Time:</b>	10:05 AM
<b>Name of School Corporation:</b>	INTERNATIONAL LEADERSHIP SCHOOL			<b>Corp ID:</b>	ILS02
<b>Address of School Corporation:</b>	6413 N Clinton				
<b>City:</b>	Fort Wayne	<b>Zip:</b>	46825	<b>County Number:</b>	2
<b>VIN:</b>	1BABNCPA7DF292138	<b>License Number:</b>	B218T	<b>Bus Number:</b>	173
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2012	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	D	<b>Mileage:</b>	102503	<b>Year:</b>	2012
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Eric Egbert	<b>PE:</b>	7006

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-5	See Notes: Any defect inspector deems a violation not listed
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
56-1-4	See Notes: Any defect inspector deems a violation not listed
70-1-12	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
20-1-2	Excessive effort is needed to open the emergency door
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (1/2) inch in diameter.
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with**

**a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**