

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	10/4/2022	Time:	12:21 PM		
Name of School Corporation:	DELAWARE COMM. SCHOOL CORP.			Corp ID:	181875		
Address of School Corporation:	7821 SR 3 N						
City:	Muncie	Zip:	47303	County Number:	18		
VIN:	4DRBUC8N0JB494103		License Number:	14765	Bus Number:	1744	
Make of Body:	IC Corporation	Year:	2017	Make of Chassis:	IC Corporation	Year:	2018
Bus Type:	C			Mileage:	79149		
Inspection Status:	R	Inspected By:	Steve Spallinger	PE:	6921		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
71-1-1	There are loose, broken or frayed wires
62-1-2	One (1) taillight or one (1) brake light does not function
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
21-1-1	Any belt is badly chaffed, cracked, broken or missing
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.