

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/6/2022	Time:	10:41 AM		
Name of School Corporation:	ELKHART COMMUNITY SCHOOLS			Corp ID:	202305		
Address of School Corporation:	2720 California Rd						
City:	Elkhart	Zip:	46514	County Number:	20		
VIN:	4DRBWTAR9MB443226		License Number:	24414	Bus Number:	102	
Make of Body:	IC Corporation	Year:	2020	Make of Chassis:	IC Corporation	Year:	2021
Bus Type:	D			Mileage:	2857		
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
68-1-3	Reservoir is empty

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.