## REPORT OF SCHOOL BUS INSPECTION

Type of Semi-Annual Date: 10/7/2022 Time: 12:16 PM

Name of School Corporation: KOKOMO SCHOOL CORPORATION Corp ID: 343500

Address of School Corporation: 620 W Deffenbaugh

 City:
 Kokomo
 Zip:
 46901
 County Number:
 34

 VIN:
 4DRBUSKN0BB354511
 License Number:
 74865
 Bus Number:
 215

Make of Body: Year: 2010 Make of Chassis: IC Corporation Year: 2010

Bus Type: C Mileage: 174541

Inspection Status: O Inspected By: Randy McPike PE: 7018

## **Violations - Rejected**

<u>Code</u>	<u>Description</u>
70-1-7	Any emergency window is too difficult to open
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
68-1-1	Washers do not function properly in any manner
U/_1_1	Not equipped with two lights mounted over the special service entrance door that are operable from the door area and illuminate the special service entrance door area
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
46-1-2	Any seat back or bottom is loose

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
-----------------	--------------------

Warning lights fail to operate correctly

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.