

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/7/2022	Time:	12:16 PM		
Name of School Corporation:	KOKOMO SCHOOL CORPORATION			Corp ID:	343500		
Address of School Corporation:	620 W Deffenbaugh						
City:	Kokomo	Zip:	46901	County Number:	34		
VIN:	4DRBUSKN0BB354511		License Number:	74865	Bus Number:	215	
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2010
Bus Type:	C			Mileage:	174541		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-7	Any emergency window is too difficult to open
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
68-1-1	Washers do not function properly in any manner
97-1-1	Not equipped with two lights mounted over the special service entrance door that are operable from the door area and illuminate the special service entrance door area
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
46-1-2	Any seat back or bottom is loose

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.