REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	10/11/2022	**Time:**	10:49 AM
Name of School Corporation:	RANDOLPH SOUTHERN SCHOOL CORP.			**Corp ID:**	686805
Address of School Corporation:	One Rebel Dr				
City:	Lynn	**Zip:**	47355	**County Number:**	68
VIN:	1BAKFCPH5AF269544	**License Number:**	32890	**Bus Number:**	5
Make of Body:	Blue Bird Corporation **Year:** 2009	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2009
Bus Type:	C	**Mileage:**	71070		
Inspection Status:	R	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.