

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 10/11/2022 **Time:** 11:03 AM
Name of School Corporation: UNION SCHOOL CORPORATION **Corp ID:** 686795
Address of School Corporation: 8707 W US 36
City: Modoc **Zip:** 47358 **County Number:** 68
VIN: 1GB3G2BGXF1246267 **License Number:** 34821 **Bus Number:** 13
Make of Body: Starcraft **Year:** 2015 **Make of Chassis:** Chevrolet **Year:** 2015
Bus Type: A2 **Mileage:** 73606
Inspection Status: R **Inspected By:** Steve Spallinger **PE:** 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.