REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	**Date:**	10/11/2022	**Time:**	11:03 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1GB3G2BGXF1246267	**License Number:**	34821	**Bus Number:**	13
Make of Body:	Starcraft **Year:** 2015	**Make of Chassis:**	Chevrolet	**Year:**	2015
Bus Type:	A2	**Mileage:**	73606		
Inspection Status:	R	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**