## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	10/20/2022	Time:	10:37 AM
Name of School Address of School	Corporation: EL col Corporation:	KHART COMM 2720 Califor	UNITY SCHOO rnia Rd	LS	Corp ID:	202305
City:	Elkhart	Zip:	46514		County Number:	20
VIN:	1T7YT4A2X71289557		License Number:	30382	Bus Number:	107
Make of Body:	Thomas Built Buses, <b>Ye</b> Inc.	<b>ar:</b> 2006	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2007
Bus Type:	D		Mileage:	140918		
Inspection Status:	0	Inspected By:	Joseph Hartma	an	PE:	7257

## Violations - Rejected

Inspection Code	<u>Description</u>
68-1-1	Washers do not function properly in any manner
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.