REPORT OF SCHOOL BUS INSPECTION

Type of 10:59 Time: Post-Crash Inspection Date: 10/20/2022 Inspection: AM Name of School Corporation: **ELKHART COMMUNITY SCHOOLS** Corp ID: 202305 **Address of School Corporation:** 2720 California Rd County City: Elkhart Zip: 46514 20 Number: License VIN: 1BAKGCPA4BF278690 74998 **Bus Number:** 138 Number: Make of Blue Bird Blue Bird Year: 2010 Year: 2011 Make of Body: Corporation Chassis: Corporation **Bus Type:** С Mileage: 83879 Inspection Inspected R PE: Joseph Hartman 7257 Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

7-1-3 Air leak at proper connection

The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.