## REPORT OF SCHOOL BUS INSPECTION

Type of 8:36 Semi-Annual Time: Date: 10/25/2022 Inspection: AM Name of School Corporation: GREATER JASPER CONS. SCHOOLS 192120 Corp ID: **Address of School Corporation:** 1520 Saint Charles St County City: Jasper Zip: 47546 19 Number: License VIN: 1BABJCPH38F250953 B549F Bus Number: Number: Make of Blue Bird Blue Bird Year: 2007 Make of Body: Year: 2008 Corporation Chassis: Corporation Bus Type: D Mileage: 128941

Philip Lubbers

PE:

7703

## **Violations - Rejected**

О

Inspection

Status:

Inspection Code	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
65-1-2	The area around any warning light is not painted black
8-1-3	ABS warning light is illuminated

Inspected

By:

## **Violations - Out of Service**

Inspection

Code	<u>Description</u>
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-
	functional if 50% or more pixels are inoperable in one light.)

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.