

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 10/31/2022 **Time:** 11:27 AM
Name of School Corporation: LIBERTY-PERRY COMM. SCH. CORP. **Corp ID:** 181895
Address of School Corporation: 10401 E CR 167 S
City: Selma **Zip:** 47383 **County Number:** 18
VIN: 4DRBUAAN0EB412407 **License Number:** 6317 **Bus Number:** 3
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2014
Bus Type: C **Mileage:** 57779
Inspection Status: O **Inspected By:** Steve Spallinger **PE:** 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
7-1-3	Air leak at proper connection

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.