

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/31/2022	Time:	5:45 PM
Name of School Corporation:	NORTHERN WELLS COMM. SCHOOLS			Corp ID:	908435
Address of School Corporation:					
City:	Zip:			County Number:	90
VIN:	4UZABRFC3PCNU5456	License Number:	NEW28	Bus Number:	28
Make of Body:	Thomas Built Buses, Inc.	Year:	2022	Thomas Built Buses, Inc.	Year:
Bus Type:	C	Mileage:	9438		2023
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
3-1-7	Battery compartment door is not securely fastened.
7-1-3	Air leak at proper connection

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.