

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/1/2022	Time:	10:17 AM		
Name of School Corporation:	HAMILTON HEIGHTS SCHOOL CORP.			Corp ID:	293025		
Address of School Corporation:	PO Box 469						
City:	Arcadia	Zip:	46030	County Number:	29		
VIN:	1BABNCSA9NF378012		License Number:	24503	Bus Number:	33	
Make of Body:	Blue Bird Corporation	Year:	2021	Make of Chassis:	Blue Bird Corporation	Year:	2022
Bus Type:	D			Mileage:	26106		
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
82-1-2	See Notes: Any defect inspector deems a violation not listed
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
103-1-1	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus
51-2-1	The service door does not open or close properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.