

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	11/1/2022	<b>Time:</b>	10:40 AM
<b>Name of School Corporation:</b>	HAMILTON HEIGHTS SCHOOL CORP.	<b>Corp ID:</b>	293025		
<b>Address of School Corporation:</b>	PO Box 469				
<b>City:</b>	Arcadia	<b>Zip:</b>	46030	<b>County Number:</b>	29
<b>VIN:</b>	1BAKJCSA3KF355607	<b>License Number:</b>	22361	<b>Bus Number:</b>	24
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2019	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	57077	<b>Year:</b>	2019
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joel Flores	<b>PE:</b>	7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	The trash container is greater than a fourteen (14) quart capacity
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
59-2-1	Any stop arm light is inoperative
65-2-1	Warning lights fail to operate correctly
64-2-1	Any rear turn signal does not function properly
20-2-2	Door glass is missing
20-2-4	Emergency door is not securely fastened to body

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in**

**front of the windshield. The entrance door is behind the front wheels.**