REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	11/1/2022	**Time:**	10:40 AM
Name of School Corporation:	HAMILTON HEIGHTS SCHOOL CORP.			**Corp ID:**	293025
Address of School Corporation:	PO Box 469				
City:	Arcadia	**Zip:**	46030	**County Number:**	29
VIN:	1BAKJCSA3KF355607	**License Number:**	22361	**Bus Number:**	24
Make of Body:	Blue Bird Corporation **Year:** 2019	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2019
Bus Type:	C	**Mileage:**	57077		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
90-1-2	The trash container is greater than a fourteen (14) quart capacity
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
59-2-1	Any stop arm light is inoperative
65-2-1	Warning lights fail to operate correctly
64-2-1	Any rear turn signal does not function properly
20-2-2	Door glass is missing
20-2-4	Emergency door is not securely fastened to body

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.