

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/2/2022	Time:	8:24 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4DRBUAFPX7B346865	License Number:	B960S	Bus Number:	12
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	137873	Year:	2007
Inspection Status:	R	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.