

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/2/2022	Time:	9:54 AM		
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL		Corp ID:	141375			
Address of School Corporation:	5494 E SR 58						
City:	Elnora	Zip:	47529	County Number:	14		
VIN:	4DRBUAAP0AB184999		License Number:	B208E	Bus Number:	6	
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2010
Bus Type:	A1	Mileage:	187051				
Inspection Status:	R	Inspected By:	Philip Lubbers	PE:	7703		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.