REPORT OF SCHOOL BUS INSPECTION

Type of 10:02 Semi-Annual Date: 11/2/2022 **Time**: Inspection: AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL 141375 Corp ID: **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 4UZAAXBWX2CJ64882 B412D **Bus Number:** 14 Number: Make of Blue Bird Year: 2001 Make of Body: Freightliner Year: 2002 Corporation Chassis: **Bus Type:** С Mileage: 163195 Inspected PE: 7703 **Inspection Status:** R Philip Lubbers By:

Violations - Rejected

<u>Inspection</u>	<u>Description</u>
Code	

70-1-10 If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Inspection Code Description

Violations - Out of Service

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.