REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	11/2/2022	Time:	10:37 AM
Name of School Corporation: Address of School Corporation:		NORTH DAVIESS CO. COMM. SCHOOL 5494 E SR 58			Corp ID:	141375
City:	Elnora	Zip:	47529		County Number:	14
VIN:	1BAKFCKH56F233657		License Number:	B590C	Bus Number:	3
Make of Body:	Blue Bird Corporation	Year: 2005	Make of Chassis:	Blue Bird Corporation	Year:	2006
Bus Type:	С		Mileage:	160103		
Inspection Status:	R	Inspected By:	Philip Lubbers	3	PE:	7703

Violations - Rejected

Inspection <u>Code</u>	<u>Description</u>
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.