

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 11/3/2022      **Time:** 9:10 AM  
**Name of School Corporation:** MARQUETTE HIGH SCHOOL      **Corp ID:** 71002Z  
**Address of School Corporation:** 306 W 10th St.  
**City:** Michigan City      **Zip:** 46306      **County Number:** 46  
**VIN:** 1GBHG31R6Y1201361      **License Number:** b872aa      **Bus Number:** 1  
**Make of Body:** Chevrolet      **Year:** 2000      **Make of Chassis:** Corbeil      **Year:** 2000  
**Bus Type:**      **Mileage:** 142174  
**Inspection Status:** R      **Inspected By:** Nathan Sherer      **PE:** 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-3	There is loose or unprotected wiring in passenger area
43-1-8	Any required lettering is missing or faded.
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
2-1-3	Any back-up light lens is cracked, broken, faded or missing
2-1-1	Required back-up lights do not function.

### Violations - Out of Service

Inspection Code      Description

Bus Type      Description