REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			**Date:**	11/7/2022	**Time:**	9:50 AM
Name of School Corporation:		UNION SCHOOL CORPORATION				**Corp ID:**	686795
Address of School Corporation:		8707 W US 36					
City:	Modoc	**Zip:**	47358			**County Number:**	68
VIN:	1GBJG31K591154524			**License Number:**	80600	**Bus Number:**	14
Make of Body:	Collins Bus Corporation	**Year:**	2009	**Make of Chassis:**	Chevrolet	**Year:**	2009
Bus Type:	A2			**Mileage:**	90875		
Inspection Status:	R	**Inspected By:**	Steve Spallinger			**PE:**	6921

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
30-1-1	There are any holes in the floor

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**