

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/7/2022	Time:	10:06 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			Corp ID:	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	Zip:	47358	County Number:	68
VIN:	4drbuskp1bb262051	License Number:	7134	Bus Number:	5
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation
Year:	2009	Year:	2009	Year:	2009
Bus Type:	C	Mileage:	106030		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
40-1-1	Any required instrument or gauge is missing. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.