REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	11/7/2022	**Time:**	10:50 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1HVBBABP7YH307899	**License Number:**	17633	**Bus Number:**	4
Make of Body:	Blue Bird Corporation **Year:** 2000	**Make of Chassis:**	IC Corporation	**Year:**	2001
Bus Type:	C	**Mileage:**	90300		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
35-1-1	A heater motor is not operating properly
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.