

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/16/2022	Time:	12:41 PM		
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300		
Address of School Corporation: 5808 E Administration Rd							
City:	Marengo	Zip:	47140	County Number:	13		
VIN:	1GB3G3BGXE1135206	License Number:		23241	Bus Number:	41	
Make of Body:	Chevrolet	Year:	2013	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2015
Bus Type:	A2	Mileage:		Unknown			
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-1	Turn signals are not properly mounted
64-1-4	Any front turn signal does not function properly

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.