REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	11/16/2022	Time:	12:41 PM
Name of School Corporation:	CRAV	WFORD CO. C	OMM. SCHOOL C	CORP	Corp ID:	131300
Address of Schoo	l Corporation:	5808 E Admir	nistration Rd			
City:	Marengo	Zip:	47140		County Number:	13
VIN:	1GB3G3BGXE1	1135206	License Number:	23241	Bus Number:	41
Make of Body:	Chevrolet Year:	2013	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2015
Bus Type:	A2		Mileage:	Unknown		
Inspection Status:	0	Inspected By:	Philip Lubbers		PE:	7703

Violations - Rejected

Inspection Code	<u>Description</u>
-----------------	--------------------

64-1-1 Turn signals are not properly mounted

64-1-4 Any front turn signal does not function properly

Violations - Out of Service

Inspection Code	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.