## REPORT OF SCHOOL BUS INSPECTION

Type of 1:09 Semi-Annual Time: Date: 11/16/2022 Inspection: PM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300 **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1BAKFCPA67F241201 B951B Bus Number: 22 Number: Make of Blue Bird Blue Bird Year: 2006 Make of Body: Year: 2007 Corporation Chassis: Corporation **Bus Type:** С Mileage: Unknown Inspection Inspected R PE: Philip Lubbers 7703 Status: By:

## **Violations - Rejected**

Increation Code

mspection code	<u>Description</u>
20-1-10	See Notes: Any defect inspector deems a violation not listed
1111	Any marker light or long is missing eracked foded wrong color or incorporative

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Description

64-1-4 Any front turn signal does not function properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.