

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/17/2022	Time:	9:38 AM		
Name of School Corporation:	MUNCIE COMMUNITY SCHOOLS			Corp ID:	181970		
Address of School Corporation:	2501 N Oakwood						
City:	Muncie	Zip:	47304	County Number:	18		
VIN:	1GB6G2AG6A1148487		License Number:	83029	Bus Number:	6	
Make of Body:	Collins Bus Corporation	Year:	2010	Make of Chassis:	Chevrolet	Year:	2010
Bus Type:				Mileage:	31820		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
23-1-1	Any part is missing, including originally equipped heat shields

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk
8-2-1	There is no brake certification, or the certification has expired or is not signed
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

Bus Type Description