

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 11/17/2022	<b>Time:</b> 9:56 AM
<b>Name of School Corporation:</b> MUNCIE COMMUNITY SCHOOLS	<b>Corp ID:</b> 181970	
<b>Address of School Corporation:</b> 2501 N Oakwood		
<b>City:</b> Muncie	<b>Zip:</b> 47304	<b>County Number:</b> 18
<b>VIN:</b> 1GB6G3AGXA1141385	<b>License Number:</b> 83104	<b>Bus Number:</b> 8
<b>Make of Body:</b> Collins Bus Corporation	<b>Year:</b> 2010	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2010	<b>Mileage:</b> 42451	<b>Year:</b> 2010
<b>Bus Type:</b>		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Steve Spallinger	<b>PE:</b> 6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
15-1-1	The defroster system is not working properly.
62-1-10	See Notes: Any defect inspector deems a violation not listed
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-3	Any emergency window will not open
32-2-3	Tank cap is missing
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description