## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection**: Re-Inspection **Date**: 11/28/2022 **Time**: 1:49 PM **Name of School Corporation**: MARQUETTE HIGH SCHOOL **Corp ID**: 71002Z

Address of School Corporation: 306 W 10th St.

City:Michigan CityZip:46306County Number: 46VIN:1GBHG31R6Y1201361License Number: b872aaBus Number: 1Make of Body:Chevrolet Year: 2000Make of Chassis: CorbeilYear: 2000

Bus Type: Mileage: 142174

Inspection Status: R Inspected By: Tim Grayson PE: 7558

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

43-1-8 Any required lettering is missing or faded. 2-1-1 Required back-up lights do not function.

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**