REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	11/29/2022	**Time:**	11:07 AM
Name of School Corporation:	DALEVILLE COMMUNITY SCHOOLS			**Corp ID:**	181940
Address of School Corporation:	14300 W 2nd St				
City:	Daleville	**Zip:**	47334	**County Number:**	18
VIN:	1GBJG312361237848	**License Number:**	10573	**Bus Number:**	24
Make of Body:	Mid Bus, Inc. **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2005
Bus Type:	A2	**Mileage:**	106593		
Inspection Status:	R	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
29-1-4	Prohibited area line is missing or improper
29-1-5	Prohibited area sign is missing or obscured
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**