## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:12/1/2022Time:9:42 AMName of School Corporation:LAPORTE COMMUNITY SCHOOL CORP.Corp ID:464945

Address of School Corporation: 1921 A St

City:La PorteZip:46350County Number: 46VIN:4DRBUAAN6BB368943License Number: 75079Bus Number: 4Make of Body:IC Corporation Year: 2009Make of Chassis: IC Corporation Year: 2010

Bus Type: C Mileage: 153908

Inspection Status: O Inspected By: Tim Grayson PE: 7558

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.