## REPORT OF SCHOOL BUS INSPECTION

Type of 10:34 Semi-Annual Date: 12/1/2022 Time: Inspection: AM **GOSHEN COMMUNITY SCHOOLS** 202315 Name of School Corporation: Corp ID: **Address of School Corporation:** 613 E Purl St County City: Goshen Zip: 46526 20 Number: License VIN: 1T7YT4E25B1129508 74239 Bus Number: 8 Number: Thomas Built Buses, Year: 2009 Thomas Built Buses, Year: Make of Make of Body: 2011 Chassis: Inc. **Bus Type:** D Mileage: 138600 Inspection Inspected PE: 0 7257 Joseph Hartman Status: By:

## **Violations - Rejected**

| <u>Inspection</u> | Description |
|-------------------|-------------|
| Code              | Description |

The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

## **Violations - Out of Service**

| Inspection<br>Code | <u>Description</u>   |
|--------------------|--|
| 46-2-3             | Flip seat does not stay in the upright position when no passengers are seated                                  |
| 7-2-8              | There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely |

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.