REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	n	Date:	12/6/2022	Time:	1:02 PM
Name of School Address of School	Corporation: ool Corporation:	WASHINGTON 301 E Sc	N COMM. SCHOOLS outh St	S, INC.	Corp ID:	141405
City:	Washington	Zip:	47501		County Number:	14
VIN:	4UZABRFC8JCJF93	•	License Number:	24785	Bus Number:	1
Make of Body:	Thomas Built Buses, Inc.	Year: 2017	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2018
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	0	Inspecte By:	ed Philip Lubbers		PE:	7703

Violations - Rejected

<u>inspection</u>	Description
Code	<u>Description</u>

The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	<u>Description</u>
11-2-2	A bumper does not meet manufactures specifications
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.