

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Registration	<b>Date:</b> 12/7/2022	<b>Time:</b> 8:37 AM
<b>Name of School Corporation:</b> CAREER ACADEMY SOUTH BEND	<b>Corp ID:</b> 2400828	
<b>Address of School Corporation:</b> 3801 Crescent Circle		
<b>City:</b> South Bend	<b>Zip:</b> 46628	<b>County Number:</b> 71
<b>VIN:</b> 4DRBUC8N8GB724589	<b>License Number:</b> temp725282	<b>Bus Number:</b> 99
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2014	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2015	<b>Mileage:</b> 100000	<b>PE:</b> 8022
<b>Bus Type:</b> C	<b>Inspected By:</b> Travis Harrold	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-6	Rear seats are too close to the body
29-1-5	Prohibited area sign is missing or obscured
29-1-4	Prohibited area line is missing or improper
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
45-2-1	The bus with a body build date of January 1, 2006 or after is not equipped with the noise suppression switch. EXEMPTION Type A buses - w/out noise making devices other OEM accessories not including two-way, AM/FM, Satellite, or similar.
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.