REPORT OF SCHOOL BUS INSPECTION

Type of 10:51 Time: Re-Inspection Date: 12/8/2022 Inspection: AM CRAWFORDSVILLE COMM. SCHOOLS 545855 Name of School Corporation: Corp ID: **Address of School Corporation:** 1000 Fairview Ave County City: Crawfordsville Zip: 47933 54 Number: License VIN: 1T7YT4C2681297914 20456 Bus Number: 28 Number: Thomas Built Buses, Year: 2007 Thomas Built Buses, Year: Make of Make of Body: 2008 Chassis: Inc. Bus Type: D Mileage: 118563 Inspection Inspected 0 PE: 7421 Nate King Status: By:

Violations - Rejected

Inspection Code Description

22-1-1 A dripping oil or fluid leak

2-1-4 LED type lights have 25% or more of the pixels inoperable in any one light

Violations - Out of Service

| Inspection Code | <u>Description</u> |
|--------------------|---|
| 59-2-6 | LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in |
| | the word "STOP" equals one light.) |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.