

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 12/9/2022	Time: 9:28 AM
Name of School Corporation: RENSSELAER CENTRAL SCHOOL CORP	Corp ID: 373815	
Address of School Corporation: 900 E Washington		
City: Rensselaer	Zip: 47978	County Number: 37
VIN: 4DRBUAAP0BB281184	License Number: SB74247	Bus Number: 7
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation
Year: 2009	Mileage: 157136	Year: 2009
Bus Type: C		
Inspection Status: O	Inspected By: Tim Grayson	PE: 7558

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.