REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	12/12/2022	Time:	10:41 AM
Name of School Address of Scho	•	YORKTOWN COM 8800 W Smi		OOLS	Corp ID:	181910
City:	Yorktown	Zip:	47396		County Number:	18
VIN:	1bakjcpa2bf278673	3	License Number:	0984	Bus Number:	26
Make of Body:	Blue Bird Corporation	Year: 2010	Make of Chassis:	Blue Bird Corporation	Year:	2010
Bus Type:	С		Mileage:	81316		
Inspection Status:	0	Inspected By:	Steve Spallin	ger	PE:	6921

Violations - Rejected

Inspection Code	<u>Description</u>
-----------------	--------------------

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

2-1-1 Required back-up lights do not function.

Violations - Out of Service

<u>Inspection</u>	Description
Code	<u>Description</u>

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.