REPORT OF SCHOOL BUS INSPECTION

Type of 11:58 Time: Re-Inspection Date: 12/12/2022 Inspection: AM Name of School Corporation: YORKTOWN COMMUNITY SCHOOLS 181910 Corp ID: **Address of School Corporation:** 8800 W Smith St County City: Yorktown Zip: 47396 18 Number: License VIN: 1bakjcpa2bf278673 0984 **Bus Number:** 26 Number: Make of Blue Bird Blue Bird Year: 2010 Make of Body: Year: 2010 Corporation Chassis: Corporation **Bus Type:** С Mileage: 81316 Inspection Inspected 0 PE: Steve Spallinger 6921 Status: By:

Violations - Rejected

Inspection Code Description

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection

Code	<u>Description</u>
	There is body damage which could cause injury to persons near the bus (e.g. jagged
24-2-1	metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the

Decembeles

bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.