

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	12/13/2022	Time:	10:19 AM		
Name of School Corporation:	BAUGO COMMUNITY SCHOOLS			Corp ID:	202260		
Address of School Corporation:	29125 CR 22 W						
City:	Elkhart	Zip:	46517	County Number:	20		
VIN:	1BAKJCPA7BF278671		License Number:	860	Bus Number:	8	
Make of Body:	Blue Bird Corporation	Year:	2010	Make of Chassis:	Blue Bird Corporation	Year:	2011
Bus Type:	C			Mileage:	88084		
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
34-1-1	Any headlight is inoperative
37-1-1	The horn does not operate at all
64-1-4	Any front turn signal does not function properly
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus
64-2-1	Any rear turn signal does not function properly
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.