## REPORT OF SCHOOL BUS INSPECTION

Type of Re-Inspection Date: 12/13/2022 Time: 10:57 AM

Name of School Corporation: BAUGO COMMUNITY SCHOOLS Corp ID: 202260

Address of School Corporation: 29125 CR 22 W

 City:
 Elkhart
 Zip:
 46517
 County Number:
 20

 VIN:
 4DRBUAAP09B670952
 License Number:
 Bus Number:
 4

Make of Body: IC Corporation Year: 2007 Make of Chassis: IC Corporation Year: 2009

Bus Type: C Mileage: 93913

Inspection Status: R Inspected By: Joseph Hartman PE: 7257

## **Violations - Rejected**

Inspection Code Description

The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile) 4 2"x5yd gauze stretch material (panetorile) 3 eval eve pade (sterile) 2

(sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2

triangular bandages, 1 instruction.

76-1-2 The back – up warning alarm is not 97 DBA (+/- 4 DBA

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.