## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	12/13/2022	Time:	11:14 AM
Name of School Corporation: Address of School Corporation:		BAUGO COMMUNITY SCHOOLS 29125 CR 22 W			Corp ID:	202260
City:	Elkhart	Zip:	46517		County Number:	20
VIN:	1BAKJCPA3BF278679		License Number:	859	Bus Number:	13
Make of Body:	Blue Bird Corporation	<b>Year:</b> 2010	Make of Chassis:	Blue Bird Corporation	Year:	2011
Bus Type:	С		Mileage:	68514		
Inspection Status:	0	Inspected By:	Joseph Hartma	ın	PE:	7257

## **Violations - Rejected**

Inspection

Inspection Code	<u>Description</u>
	The first aid kit is not complete: One (1) package adhesive bandages; containing a

of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads 28-1-4 (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

a total

41-1-2 Any interior protrusions have sharp edges or corners

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any
1-2-2	two (2) brakes measure less than 1/4 inch beyond the readjustment limit

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.