

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	12/13/2022	Time:	12:13 PM
Name of School Corporation:	BAUGO COMMUNITY SCHOOLS			Corp ID:	202260
Address of School Corporation:	29125 CR 22 W				
City:	Elkhart	Zip:	46517	County Number:	20
VIN:	1T7YT4A2591113289	License Number:	32471	Bus Number:	1
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	120529
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
79-1-3	If equipped the emergency warning buzzer does not sound
20-1-4	Rubber seals are missing or loose
7-1-3	Air leak at proper connection

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.