REPORT OF SCHOOL BUS INSPECTION

Type of 12:42 Time: Re-Inspection Date: 12/13/2022 Inspection: PM Name of School Corporation: **BAUGO COMMUNITY SCHOOLS** Corp ID: 202260 **Address of School Corporation:** 29125 CR 22 W County City: Elkhart Zip: 46517 20 Number: License VIN: 1BAKJCPA3BF278679 859 **Bus Number:** 13 Number: Make of Blue Bird Blue Bird Year: 2010 2011 Make of Body: Year: Corporation Chassis: Corporation Bus Type: С Mileage: 68514 Inspection Inspected R PE: Joseph Hartman 7257 Status: By:

Violations - Rejected

Inspection Code Description

The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.