REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	12/15/2022	Time:	9:13 AM
Name of School	•		COMMUNITY SC	CHOOLS	Corp ID:	928625
Address of Scho	ool Corporation:	222 W. Ti	222 W. Tulley St.			
City:	Churbusco	Zip:	46723		County Number:	92
VIN:	1BABKCPA88F255257		License Number:	30961	Bus Number:	9
Make of Body:	Blue Bird Corporation	Year: 2007	Make of Chassis:	Blue Bird Corporation	Year:	2008
Bus Type:	D		Mileage:	88161		
Inspection Status:	R	Inspecte By:	d Joseph Hartm	nan	PE:	7257

Violations - Rejected

Inspection <u>Code</u>	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.