REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	12/15/2022	Time:	10:13 AM
Name of School Address of Scho	•	•	EEN Co	OMMUNITY SC by St.	HOOLS	Corp ID:	928625
City:	Churbusco	Zip:		46723		County Number:	92
VIN:	1BABLCPA2AF273	3661		License Number:	72279	Bus Number:	22
Make of Body:	Blue Bird Corporation	Year: 2009		Make of Chassis:	Blue Bird Corporation	Year:	2010
Bus Type:	D			Mileage:	128222		
Inspection Status:	0	Insp By:	ected	Joseph Hartm	an	PE:	7257

Violations - Rejected

Inspection Code	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
7-1-3	Air leak at proper connection
15-1-1	The defroster system is not working properly.

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.