

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/16/2022	Time:	11:59 AM
Name of School Corporation:	PLYMOUTH COMMUNITY SCHOOL CORP			Corp ID:	505485
Address of School Corporation:	701 E Berkley St				
City:	Plymouth	Zip:	46563	County Number:	50
VIN:	4DRBUC8N1JB055265			License Number:	8609
Make of Body:	IC Corporation	Year:	2017	Make of Chassis:	IC Corporation
Bus Type:	C			Year:	2018
Inspection Status:	O	Inspected By:	Travis Harrold	PE:	8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative
64-1-2	A lens is cracked, missing or wrong color
65-1-1	Any lens is cracked, broken or discolored
65-1-6	LED Lights have 25% to 49% of pixels inoperable.
20-1-2	Excessive effort is needed to open the emergency door
2-1-3	Any back-up light lens is cracked, broken, faded or missing
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
46-2-2	Any seat is broken or not attached to the floor
64-2-2	LED type lights have 50% or more of the pixels inoperable in any one rear light
20-2-4	Emergency door is not securely fastened to body
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.